





Master



Slave



TP4	GND
TP6	Pin17/RXER (CLK-Out in TestMode)
TP7	Pin20/CLK_IN_OUT
TP3	GND
TP1	Pin25/REF_CLK



Link-Up Master

Link-Up Slave

No Link Master

No Link Slave